Milgard
WINDOWS & DOORS

⊘ DIY SELF-SERVICE GUIDE

HOW TO CLEAN WEEP HOLES ON A
VINYL SLIDING DOOR

Materials Required:

Putty Knife, Pipe Cleaner

**Difficulty:**

Easy

Time Requirement:

5 minutes

INSTRUCTIONS:

1. From exterior of house, use a putty knife starting on either side, pop the weep hole covers out on both sides.

WEEP HOLE COVERS

2. Using a pipe cleaner, insert it into the weep hole and wiggle to free up any debris.

3. After cleaning weep hole, pour some water into the track to test the weep hole and make sure it is completely clean.

INSERT PIPE CLEANER

POUR WATER INTO TRACK

4. Replace weep hole covers by placing one side in first and pressing them into place.